



High-Pro Company Ltd.
www.hpccoil.com

New Product Announcement

June 2023

Introducing the new ignition coils with close-to-OE performance and quality!

For more product information and quotation, please visit our website at www.hpccoil.com and contact us at hipro@high-pro.com.tw



** Please follow us on our website  and Facebook  .

10-313



504085566, 0221504025

Iveco EuroCargo.....11-91
Iveco Stralis.....02

10-314



55229959, 0221504036

Alfa Romeo Giulietta.....10-
Alfa Romeo Mito.....08-
Chrysler Delta.....08-
Fiat 500X.....15-14
Fiat Bravo.....14-10
Fiat Punto.....12-
Jeep Renegade.....14-
Lancia Delta III.....14-10

10-318



24563798
F01R00A075

Chinese Car
Baojun 530/560/730 1.5T

10-319



22448-1F700
0221504017
ZS337

Nissan Micra II (K11).....03-92

10-320



2730003150

Kia K900.....16-15
Kia Soul II.....16-14

10-321



3705010H01

Chinese Car
For Changan Star 473 Engine



11-282

31437796, 31492125, 50755030,
8888481265

- Volvo XC40 T2.....19-
- Volvo XC40 T3.....18-
- Volvo XC40 T4.....20-
- Volvo XC40 T5.....19-



11-288

55496698, 79011003

- Buick Encore GX21-20
- Chevrolet Onix.....21-20
- Chevrolet Tracker.....21



11-020

UF536, C1689
 BERU
 ZS041
 Bosch
 0986221007
 Mercedes Benz
 0001501780, 0001502880, A0001501780,
 A0001502880, 0040100039

- Mercedes-Benz C180.....02-00
- Mercedes-Benz C200.....02-00
- Mercedes-Benz C230.....02-01
- Mercedes-Benz CLK200.....02-00
- Mercedes-Benz CLK230.....02-00
- Mercedes-Benz E200.....03-00
- Mercedes-Benz SLK200.....04-00
- Mercedes-Benz SLK230.....04-00



20-040

UF392
 0001500480, 0001500580, 0001586803,
 0221505437

- Mercedes Benz C220..... 96-94



High-Pro Co. Ltd. (HPC)

An IATF 16949: 2016 certified Company

Head-Office: 5F, No. 162, Lide St., Zhonghe District, New Taipei City, Taiwan
 Factory: No.23 Lane 3129, Shenzhuan Road, Sheshan Town, Songjiang District, Shanghai, China
 E-mail: hipro@high-pro.com.tw

